


Montaje

Paso 5



H- Clavo 10x10 (28x)



Montaje Cajones (4x)

Paso 7




I- Tirador (8x)



D- Tornillo Ø3,5x25 (8x)



N- Tambor (8x)




Montaje Cajones (4x)

Paso 6



G- Tornillo Ø4,5x45 (6x)



E- Tornillo
Ø3,5x12 (16x)



C- Corrediza
(4x)

